

# Indoor air sealing of office spaces | Lappeenranta



## Description

The indoor air repair of the office premises was carried out with ElaProof products. The repair included sealing repairs to the frame structures. The goal is to secure good indoor air by repairing the element seams of the outer wall element. Quality control was performed with tracer tests. Lifetime target: 20 years

## Information

The site has a typical 1980s concrete-wool-concrete frame. The tightness of the recasts of the element joints is insufficient. By repairing them, better indoor air quality, improved thermal comfort and the building physical function of the structures are achieved.

## Project information

**Project:** Indoor Air Sealing

**Address:** Lappeenranta, Finland

**Material:** concrete-wool-concrete frame

**Contractor:** AT Rakennus Oy

**Supervisor:** Paloniitty Oy, Sauli Paloniitty

**Time and city:** 12/2020 | Lappeenranta

## Products used in the project

- [ElaProof Indoor](#)
- [ElaProof Base Fabric](#)
- [ElaProof Primer](#)

