

# Indoor air sealing of a townhouse apartment



## Arbeidserklæring

A microbial odor was detected in the indoor air of a townhouse apartment, the cause of which turned out to be a leak coming from the soil at the border between the floor and the plinth. Structure opened and microbial odorous materials removed and air leakage sealed with ElaProof Indoor. The space has been dust cleaned and ozonated. The moisture content of the structure was measured with structural moisture measurements. The renewal of the structure was carried out according to the plans.

## Vareinformasjon

**Kunde:** Private house

**Mål:** Indoor Air Sealing

**Materiale:** Concrete

**Entreprenør:** Paloniitty Oy

**Veileder:** Paloniitty Oy, Sauli Paloniitty

**Tid og sted:** 08/2020 |

## Produkter brukt på destinasjonen

- [ElaProof Indoor](#)
- [ElaProof Base Fabric](#)
- [ElaProof Primer](#)

