

Indoor air sealing of a townhouse apartment



Description

A microbial odor was detected in the indoor air of a townhouse apartment, the cause of which turned out to be a leak coming from the soil at the border between the floor and the plinth. Structure opened and microbial odorous materials removed and air leakage sealed with ElaProof Indoor. The space has been dust cleaned and ozonated. The moisture content of the structure was measured with structural moisture measurements. The renewal of the structure was carried out according to the plans.

Project information

Client: Private house

Project: Indoor Air Sealing

Material: Concrete

Contractor: Paloniitty Oy

Supervisor: Paloniitty Oy, Sauli Paloniitty

Time and city: 08/2020 |

Products used in the project

- [ElaProof Indoor H](#)
- [ElaProof Base Fabric](#)
- [ElaProof Primer](#)



All the information presented above is based on research results, our current knowledge and experience. They do not remove the responsibility of the user of the product to carry out his own tests and experiments, so that all factors and conditions that may affect the installation and use of the products should be considered. No guarantees regarding the properties or suitability of the product for specific purposes can be given based on this information. All descriptions, drawings, photos, information, proportions, portion sizes, weights, etc. are indicative. We are not responsible if the product is used contrary to the instructions presented here. It is the responsibility of the user of the product to test the suitability of the product for the purpose of use. We are only responsible for the quality of the product and guarantee that it will pass our critical quality control. Product information is updated regularly, however, it is the user's responsibility to obtain the latest valid product information, which can be found at www.elaproof.com. We reserve the right to make changes. © Build Care Oy