

Balcony waterproofing | Vantaa



Description

There are leaks in the wall-floor boundary on the balcony of a detached house in Vantaa. The base was carefully cleaned and primed with ElaProof Primer. The balcony was carefully sealed using ElaProof Base Fabric and ElaProof H.

Project information

Client: Private house

Project: Balcony waterproofing

Address: Rubiininkhä, Vantaa, Finland

Material: Concrete

Contractor: Laatukodit Uusimaa Oy

Time and city: 06 / 2020 | Vantaa

Products used in the project

- [ElaProof Classic H](#)
- [ElaProof Primer](#)

- [ElaProof Base Fabric](#)



All the information presented above is based on research results, our current knowledge and experience. They do not remove the responsibility of the user of the product to carry out his own tests and experiments, so that all factors and conditions that may affect the installation and use of the products should be considered. No guarantees regarding the properties or suitability of the product for specific purposes can be given based on this information. All descriptions, drawings, photos, information, proportions, portion sizes, weights, etc. are indicative. We are not responsible if the product is used contrary to the instructions presented here. It is the responsibility of the user of the product to test the suitability of the product for the purpose of use. We are only responsible for the quality of the product and guarantee that it will pass our critical quality control. Product information is updated regularly, however, it is the user's responsibility to obtain the latest valid product information, which can be found at www.elaproof.com. We reserve the right to make changes. © Build Care Oy