

## Balcony waterproofing | Vantaa



### Description

There are leaks in the wall-floor boundary on the balcony of a detached house in Vantaa. The base was carefully cleaned and primed with ElaProof Primer. The balcony was carefully sealed using ElaProof Base Fabric and ElaProof H.

### Project information

**Client:** Private house

**Project:** Balcony waterproofing

**Address:** Rubiininkhä, Vantaa, Finland

**Material:** Concrete

**Contractor:** Laatukodit Uusimaa Oy

**Time and city:** 06 / 2020 | Vantaa

### Products used in the project

- [ElaProof Classic H](#)
- [ElaProof Primer](#)

- [ElaProof Base Fabric](#)

