

Indoor air sealing repair of senior apartments | Vaasa



Description

Sealing repair in connection with the basic repair: Upper floor-wall joint, hollow tile seams, penetrations, window joints and intermediate floor-wall joint.

Information

The site is a concrete sandwich element (+cavity slab) house, which was built in 1985 as a service building. Currently, the building has senior apartments, service providers and office space.

Project information

Client: Vuorikatu Senior Apartment

Project: Indoor Air Sealing

Address: Vuorikatu 2-4, Vaasa, Finland

Material: Concrete sandwich element

Contractor: Drytec Oy

Supervisor: Vahanen Rakennusfysiikka Oy, Arto Toorikka

Time and city: 07/2020 | Vaasa

Products used in the project

- [ElaProof Indoor](#)
- [ElaProof Primer](#)
- [ElaProof Base Fabric](#)

