

## Indoor air sealing | Hamina



### Description

The apartment has indoor air pollution and heat leaks. The floor coverings in the apartment were removed and the concrete surfaces were milled for the installation of ElaProof Indoor. After ElaProof Primer treatment, indoor air sealing work started at the site. The work was performed in accordance with the work instructions of the product manufacturer. The examinations carried out in the final inspection, e.g. with a thermal camera and smoke tests. The premises have been found to be compact by building health expert Jari Harju.

### Project information

**Client:** Private house

**Project:** Indoor Air Sealing

**Address:** Patterinkatu, Hamina, Finland

**Material:** Concrete

**Contractor:** Rakennus Alakangas Oy

**Supervisor:** Rakennussuunnittelu ja -valvonta Valkoinen Linja Oy, Building health expert Jari Harju

**Time and city:** 01/2020 | Hamina

## Products used in the project

- [ElaProof Indoor](#)
- [ElaProof Primer](#)
- [ElaProof Base Fabric](#)

