

# Indoor air sealing repair of senior apartments | Vaasa



## Arbejdserklæring

Sealing repair in connection with the basic repair: Upper floor-wall joint, hollow tile seams, penetrations, window joints and intermediate floor-wall joint.

## Mere information

The site is a concrete sandwich element (+cavity slab) house, which was built in 1985 as a service building. Currently, the building has senior apartments, service providers and office space.

## Vareoplysninger

**Kunde:** Vuorikatu Senior Apartment

**Mål:** Indoor Air Sealing

**Adresse:** Vuorikatu 2-4, Vaasa, Finland

**Materiale:** Concrete sandwich element

**Entreprenør:** Drytec Oy

**Tilsynsførende:** Vahanen Rakennusfysiikka Oy, Arto Toorikka

**Tid og sted:** 07/2020 | Vaasa

## Produkter brugt på destinationen

- [ElaProof Indoor H](#)
- [ElaProof Primer](#)
- [ElaProof Base Fabric](#)

