

Balcony waterproofing | Vantaa



Arbeidserklæring

There are leaks in the wall-floor boundary on the balcony of a detached house in Vantaa. The base was carefully cleaned and primed with ElaProof Primer. The balcony was carefully sealed using ElaProof Base Fabric and ElaProof H.

Vareinformasjon

Kunde: Private house

Mål: Balcony waterproofing

Adresse: Rubiininkhä, Vantaa, Finland

Materiale: Concrete

Entreprenør: Laatukodit Uusimaa Oy

Tid og sted: 06 / 2020 | Vantaa

Produkter brukt på destinasjonen

- [ElaProof Classic H](#)
- [ElaProof Primer](#)

- [ElaProof Base Fabric](#)

